




A部詳細図 S = 1 : 2

The diagram shows a pressure safety valve (PSV) on the left and a pressure gauge on the right, both connected to a common horizontal pipe. The PSV is labeled "安全弁" (Safety Valve) with an arrow pointing to it. The pressure gauge is labeled "圧力計" (Pressure Gauge) with an arrow pointing to it. The gauge has a scale from 0 to 1.0 MPa, with markings at 0.2, 0.4, 0.6, 0.8, and 1.0. The needle is pointing to approximately 0.2 MPa.

内外面 $\#320$ バフ研磨
(袴内面は縦溶接部のみバフ研磨)
袴溶接 60° 毎6ヶ所 長さ 20 mm



③				名称	ジャケット型加圧容器 圧送ユニット			
②					PCN-J-05-UT			
①	No. 21578	堀井	2021.10.25	図番	HP-1-2-0033776-①			
No.	変更番号	氏名	日付	尺度	1:4 1:2			
板金溶接組立の寸法許容差は±1%又は5mmの大きい値				参考図	-		得意先名	規格
氏名	製図	設計	検図	日東金属工業株式会社				
日付	野村	野村	承認					
	H27.10.17	H27.10.17	小野寺	小野寺				