




Technical drawing of a mechanical assembly. The drawing shows a cross-section of a component with the following dimensions and labels:

- Dimension $t1.2$ is indicated at the top right.
- Dimension 55 is indicated vertically on the right side.
- Dimension 20 is indicated horizontally at the bottom.
- Dimension $t1$ is indicated at the bottom right.
- Labels 1, 3, 4, and 5 are circled and point to specific parts of the assembly.
- Two asterisks (*) are placed near the bottom center of the assembly.

注記
内外面#320バフ研磨

③				名称	切り欠き付半割蓋（ヒラ蓋） WHB-77		
②				図番	HP-1-2-0042553-①		
①				No.	変 更 番 号	氏 名	日 付
板金溶接組立の寸法許容差は±1%又は5mmの大きい値				尺 度	1 : 6 1 : 1		
				参考図	-	得意先名	規格
製 図		設 計		検 図		承 認	
氏 名		前澤 前澤		金子		金子	
日 付		2021.8.5 2021.8.5		金子		金子	
 日東金属工業株式会社							